## P28215.A11

## IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Patentee : Werner Brennwald, et al. Certificate of Corrections Branch

Application No. : 10/525,565 Patent No.: 7,424,856

Filed: February 25, 2005 Issued: September 16, 2008

Art Unit : 3749 Examiner: Kenneth RINEHART

For : GRATE ELEMENT FOR A GRATE OF WASTE COMBUSTION

**INSTALLATION** 

## REQUEST FOR ISSUE OF CORRECTED PATENT PURSUANT TO 35 USC 254 AND 37 CFR 1.322(b)

Commissioner for Patents Office of Patent Publication Attn: Certificate of Corrections Branch PO Box 1450 Alexandria, VA 22313-1450

Sir:

This is a Supplemental Request to the Request for Certificate of Correction filed on October 17, 2008 in the above-identified patent. Patentee hereby requests the issue of a Corrected Patent.

Since among the 14 figures found in the publication of the patent, the first 13 do not correspond to the patentee's application, correction of such errors will lead to major changes to the published patent. Therefore, due to these circumstances, a reprint of the issued patent is

deemed more appropriate.

In accordance with 37 CFR 1.322(d), as the above is the Office's error and not due to the Patentee, this Request for Issue of a Corrected Patent does not require a fee. However, should a fee be required, please charge any fees and refund excess payments to Deposit Account No. 50-2929.

Thus, Patentee hereby requests a new print of a Corrected Patent according to 37 CFR 1.322(d).

Should there be any questions, the undersigned may be contacted at the below-listed telephone number.

Respectfully submitted,

Werner Brennwald, et al.

Abraham Hershkovitz

Reg. No. 45,294

Dinh X. Nguyen Reg. No. 54,923

October 29, 2008 HERSHKOVITZ & ASSOCIATES, LLC 2845 DUKE STREET ALEXANDRIA, VA 22314 (703) 370-4800 (703) 370-4809 (fax) patent@hershkovitz.net

P28215.A11